

DEPARTMENT OF HEALTH AND HUMAN SERVICES
CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 03/06/2012
FORM APPROVED
OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 155771		(X2) MULTIPLE CONSTRUCTION A. BUILDING 01 B. WING _____		(X3) DATE SURVEY COMPLETED R 03/03/2012	
NAME OF PROVIDER OR SUPPLIER FRANKLIN UNITED METHODIST COMMUNITY				STREET ADDRESS, CITY, STATE, ZIP CODE 1070 W JEFFERSON ST FRANKLIN, IN 46131			
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)			ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)		(X5) COMPLETION DATE
{K 000}	<p>INITIAL COMMENTS</p> <p>A Post Survey Revisit (PSR) to the PSR conducted on 02/14/12 to the Life Safety Code Recertification and State Licensure Survey conducted on 12/19/11 was conducted by the Indiana State Department of Health in accordance with 42 CFR 483.70(a).</p> <p>Survey Date: 03/02/12</p> <p>Facility Number: 001127 Provider Number: 155771 AIM Number: 200247220</p> <p>Surveyor: Dennis Austill, Life Safety Code Survey Supervisor</p> <p>At this PSR survey, Franklin United Methodist Community was found in compliance with Requirements for Participation in Medicaid, 42 CFR Subpart 483.70(a), Life Safety from Fire and the 2000 edition of the National Fire Protection Association (NFPA) 101, Life Safety Code (LSC), Chapter 19, Existing Health Care Occupancies and 410 IAC 16.2.</p> <p>The Franklin United Methodist Community consists of four separate buildings constructed at four different times. Building # 1 built in 1957 is a three story, fully sprinklered building of Type I (332) construction with a basement. Building # 2 built in 1980 is a three story, fully sprinklered building of Type I (332) construction with a basement. Building # 3 built in 1992 is a one story, fully sprinklered building of Type I (332) construction with a basement. Building # 4 built in 2000 is a three story, fully sprinklered building of Type I (332) construction. Because all</p>			{K 000}			

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

TITLE

(X6) DATE

Any deficiency statement ending with an asterisk (*) denotes a deficiency which the institution may be excused from correcting providing it is determined that other safeguards provide sufficient protection to the patients. (See instructions.) Except for nursing homes, the findings stated above are disclosable 90 days following the date of survey whether or not a plan of correction is provided. For nursing homes, the above findings and plans of correction are disclosable 14 days following the date these documents are made available to the facility. If deficiencies are cited, an approved plan of correction is requisite to continued program participation.

DEPARTMENT OF HEALTH AND HUMAN SERVICES
CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 03/06/2012
FORM APPROVED
OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 155771		(X2) MULTIPLE CONSTRUCTION A. BUILDING 01 B. WING _____		(X3) DATE SURVEY COMPLETED R 03/03/2012	
NAME OF PROVIDER OR SUPPLIER FRANKLIN UNITED METHODIST COMMUNITY				STREET ADDRESS, CITY, STATE, ZIP CODE 1070 W JEFFERSON ST FRANKLIN, IN 46131			
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)			ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)		(X5) COMPLETION DATE
{K 000}	<p>Continued From page 1</p> <p>buildings are the same type of construction, the facility was surveyed as one building.</p> <p>The facility has a fire alarm system with smoke detection in the corridors, spaces open to the corridors and only in resident sleeping rooms on the Dementia unit. The healthcare portion of the facility has a capacity of 147 and had a census of 95 at the time of this survey.</p> <p>Quality Review by Robert Booher, Life Safety Code Specialist-Medical Surveyor on 03/05/12.</p>			{K 000}			